

Event Number: 1107110105 Code Revision: 01/14/2004		STATE OF NEVADA TRAFFIC ACCIDENT REPORT SCENE INFORMATION SHEET <small>Revised 1/14/04</small>			Accident Number: NHP-1107110105 <input type="checkbox"/> Property <input checked="" type="checkbox"/> Injury <input type="checkbox"/> Fatal	
<input type="checkbox"/> Urban <input checked="" type="checkbox"/> Rural	<input type="checkbox"/> Emergency Use <input type="checkbox"/> Office Report	<input type="checkbox"/> Preliminary Report <input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Resubmission <input type="checkbox"/> Supplement Report	<input type="checkbox"/> Hit and Run <input type="checkbox"/> Private Property	Agency Name: 1 - DPS Nevada Highway Patrol	
Collision Date 7/11/2011	Time 04:00	Day MONDAY	Beat / Sector LP86	<input checked="" type="checkbox"/> County LINCOLN	<input type="checkbox"/> City	Surface <input checked="" type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Gravel <input type="checkbox"/> Dirt <input type="checkbox"/> Other
Mile Marker 25	# Vehicles 1	# Non Motorists 0	# Occupants 1	# Fatalities 0	# Injured 1	# Restrained 0
Occurred On: (Highway # or Street Name) <input type="checkbox"/> 1) Parking Lot SR318						Intersection <input type="checkbox"/> Four Way <input type="checkbox"/> > Four Way <input type="checkbox"/> T <input type="checkbox"/> Y <input type="checkbox"/> Roundabout <input type="checkbox"/> Other
At Intersection With: <input checked="" type="checkbox"/> Or 105 <input checked="" type="checkbox"/> Feet <input type="checkbox"/> Miles <input checked="" type="checkbox"/> Approximate						Access Control <input checked="" type="checkbox"/> None <input type="checkbox"/> Full <input type="checkbox"/> Partial
Roadway Character <input checked="" type="checkbox"/> Curve & Grade <input type="checkbox"/> Curve & Hillcrest <input type="checkbox"/> Curve & Level <input type="checkbox"/> Straight & Grade <input type="checkbox"/> Straight & Hillcrest <input type="checkbox"/> Straight & Level <input type="checkbox"/> Unknown <input type="checkbox"/> Other		Roadway Conditions <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Slush <input type="checkbox"/> Icy <input type="checkbox"/> Standing Water <input type="checkbox"/> Wet <input type="checkbox"/> Moving Water <input type="checkbox"/> Snow <input type="checkbox"/> Unknown <input type="checkbox"/> Sand / Mud / Oil / Dirt / Gravel <input type="checkbox"/> Other	Total Thru Lanes Main Road <input type="checkbox"/> One <input checked="" type="checkbox"/> Two <input type="checkbox"/> Three <input type="checkbox"/> Four <input type="checkbox"/> Five <input type="checkbox"/> > 5	Average Roadway Widths Travel Lane: 12 Ft Storage / Turn Lane: 0 Ft Median: 0 Ft Paved Shoulder Inside: 3 Outside: 3	Roadway Grade <input checked="" type="checkbox"/> Not Determined <input type="checkbox"/> Relatively Level Roadway <input type="checkbox"/> Up Slope (+) <input type="checkbox"/> Down Slope (-) Relative To: _____ Grade: _____ %	
Pavement Markings and Type Centerline, Broken Yellow: 1 Centerline, Solid Yellow: _____ Centerline, Double Yellow: _____ Lane Line, Broken White: _____ Lane Line, Solid White: 1 Other: _____ No Passing, Either Direction: <input type="checkbox"/> None Turn Arrow Symbols: <input type="checkbox"/> Unknown Center Turn Lane Line: _____ Edge Line, Left, Yellow: _____ Edge Line, Right, White: 1				Highway Description <input checked="" type="checkbox"/> Two-Way, Not Divided <input type="checkbox"/> Two-Way, Div., Unpro. Median <input type="checkbox"/> Two-Way, Div., Median Barrier <input type="checkbox"/> One-Way, Not Div. <input type="checkbox"/> Unknown <input type="checkbox"/> Off Road		
Light Conditions <input type="checkbox"/> Dusk <input type="checkbox"/> Dawn <input type="checkbox"/> Daylight <input type="checkbox"/> Unknown <input type="checkbox"/> Other		Vehicle Collision Type <input type="checkbox"/> Head On <input type="checkbox"/> Rear to Rear <input type="checkbox"/> Rear End <input type="checkbox"/> Backing <input type="checkbox"/> Angle <input type="checkbox"/> Sideswipe - Meeting <input type="checkbox"/> Sideswipe - Overtaking <input checked="" type="checkbox"/> Non - Collision <input type="checkbox"/> Unknown		Location of First Event <input type="checkbox"/> Travel Lane <input type="checkbox"/> Turn Lane <input type="checkbox"/> Gore <input type="checkbox"/> Median <input checked="" type="checkbox"/> Inside Shoulder <input type="checkbox"/> Outside Shoulder <input type="checkbox"/> Intersection <input type="checkbox"/> Private Property <input type="checkbox"/> Roadside <input type="checkbox"/> Other		
Highway / Environment Factors <input checked="" type="checkbox"/> None <input type="checkbox"/> Shoulders <input type="checkbox"/> Weather <input type="checkbox"/> Road Obstruction <input type="checkbox"/> Debris <input type="checkbox"/> Worn Traffic Surface <input type="checkbox"/> Glare <input type="checkbox"/> Wet, Icy, Snow, Slush <input type="checkbox"/> Other Highway <input type="checkbox"/> Other Environmental <input type="checkbox"/> Ruts, Holes, Bumps <input type="checkbox"/> Active Work Zone <input type="checkbox"/> Inactive Work Zone <input type="checkbox"/> Animal In Roadway <input type="checkbox"/> Unknown			Property Damage To Other Than Vehicle Describe Property Damage: ONE STEEL ROADWAY MARKER Owner's Name (Last First Middle): NEVADA OF TRANSPORTATION <input checked="" type="checkbox"/> 1) Owner Notified DEPARTMENT Owner's Address: (Street Address City, State Zip) US93 MMLN39 ALAMO NV 89001			
First Harmful Event Code #: 308 Description: 309 HIGHWAY TRAFFIC SIGN POST						
Description of Accident / Narrative V1, A COMMERCIAL MOTOR VEHICLE, TANKER HAULING HAZMAT, WAS NORTHBOUND ON SR-318. V1 WAS ENTERING A RIGHT HAND CURVE, BUT DID NOT TURN. V1 CROSSED THE CENTER LINE AND TRAVELED INTO THE SOUTHBOUND LANE. V1 TRAVELED OFF THE WEST ROADWAY EDGE AND ON TO THE WEST DIRT SHOULDER. THE FRONT OF V1 STRUCK A STEEL ROADWAY MARKER POST. V1 ROTATED CLOCKWISE AND TRAVELED DOWN A DIRT EMBANKMENT. THE FRONT OF V1 FURROWED IN AND V1 ROTATED CLOCKWISE. THE TRAILING UNIT DETACHED FROM V1 AND ROLLED OVER. V1 CAME TO REST AT THE BOTTOM OF THE						
Investigation Complete <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Photos Taken <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Scene Diagram <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Statements# <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No 1	Date Notified 7/11/2011	Time Notified 04:05	Arrival Date 7/11/2011
Investigator(s) 485 GUY DAVIS		ID Number 485	Date 7/11/2011	Reviewed By 142 ROBERT OAKDEN	Date Reviewed 7/21/2011	Page 1 of 4

Event Number:

1107110105

STATE OF NEVADA
TRAFFIC ACCIDENT REPORT
SCENE INFORMATION SHEET
Revised 5/21/03

Accident Number:
NHP-1107110105

Agency Name:
1 - DPS Nevada Highway Patrol

Description of Accident / Narrative Continuation

DIRT EMBANKMENT, IN A NATURAL DESERT AREA, ON ITS WHEELS, FACING NORTHEAST. THE TRAILING UNIT CAME TO REST JUST SOUTH OF V1, IN THE NATURAL DESERT AREA, ON ITS RIGHT SIDE, FACING NORTHEAST. HAZMAT WAS RELEASED FROM THE TANKER. V1 AND THE TANKER CAUGHT ON FIRE. D1 STATED THAT HE CAUGHT ON FIRE INSIDE THE CAB OF V1 PRIOR TO EXITING.

Indicate North

A.I.C.:

Page

2 of 4